Enclosure (1) to Rockwell letter 881HS-1 dated 9-1-88, page 1 of 5.

GENERAL LABORATORY .

881 HILLSIDE

SURFACE SOIL SAMPLE REPORT

SAMPLES 881-1 THRU 881-10 AMMENDED REPORT

ROCKWELL INTERNATIONAL
AEROSPACE OPERATIONS
P.O. BOX 464
GOLDEN, COLORADO 80402-0464

DISTRIBUTION:

L.J. Frick R.E. Lawton

APPROVED BY: K.M. Hagglund

K.M. Haggiund

Sr. Analytical Chemist

APPROVED BY:

M.W. Hume

QC/QA Administrator

APPROVED BY:

T.H. Elmont, Manager General Chemistry

REVIEWED FOR CLASSIFICATION

BY S. L. CUNNINGHAM

Date 9/2/84 (i)

Nineteen surface soil samples from the 881 Hillside were delivered to the General Laboratory on 8-1-88 and 8-4-88. The soil samples are listed under the laboratory control numbers E88-3019 and E88-3036. This letter reports the analysis of the first ten of nineteen samples submitted for analysis.

Plutonium and uranium were selectively separated from the dissolved soil sample using ion-exchange and solvent extraction techniques. The separated element was electroplated onto a stainless steel planchet and each isotope was counted by alpha spectroscopy.

A reagent blank and an NBS standard were analyzed with this batch of samples. Data for these analyses is included in this report.

The activity of each isotope is reported based on the dry weight of the soil sample and its uncertainty is reported at the two sigma level. The theoretical minimum detectable activity (MDA) was calculated for each measurement. If the observed result was less than the MDA, the MDA is also reported. The uncertainties, denoted as +/- in the data summary, were calculated by propagating errors associated with the analyses.

## ADDENDUM

The 881 Hillside Soils Sample report submitted on 8/15/88 contained data that had been calculated incorrectly. Please replace the original report with this ammended report. In addition

to the corrections made to previously reported results, the uranium analyses of samples 881-7, 881-8 and 881-9, which were not included in the previous report, are included in this report. The quality assurance/quality control data for these analyses was also added to the report.

14

Sample Numb	ær	881 - 1	881-2	881-3	
Sample Date		7-28-88	7-28-88	7-28-88	
Pu-239,240	(pC1/g)	4.3 +/- 0.5	2.4 +/- 0.2	4.8 +/- 0.5	
U-233,234	(pCi/g)	0.56 +/- 0.26(MDA 0.86)	0.78 +/- 0.26	0.82 +/- 0.26	
U-235	(pCi/g)	0.03 +/- 0.01(MDA 0.06)	0.04 +/- 0.02	0.08 +/- 0.02	
U-238		0.60 +/- 0.15	0.86 +/- 0.15	0.91 +/- 0.15	
			,		
Sample Numb	•.	881-4	881-5	881-6	
` •		•		7-28-88	
Sample Date	•	7-28-88	7-22-88	7-20-00	
Pu-239,240	(pCi/g)	0.18 +/- 0.06	0.59 +/- 0.08	2.2 +/- 0.2	
u-233,234	(pCi/g)	1.0 +/- 0.3	0.86 +/- 0.26	1.5 +/- 0.3	
บ-235	(pCi/g)	0.03 +/- 0.02(MDA 0.05)	0.03 +/- 0.01(MDA 0.06)	0.13 +/- 0.02	
U-238	(pCi/g)	0.97 +/- 0.2	0.88 +/- 0.15	5.5 +/- 0.5	
	· · · · · · · · · · · · · · · · · · ·			•••••	
Sample Numb	· er	881-7	881-8	881-9	
Sample Date		7-29-88	7-29-88	7-29-88	
Pu-239,240	. (pCi/a) .	0.63 +/- 0.09	1.8 +/- 0.2	0.47 +/- 0.06	
•		0.74 +/- 0.26(MDA 0.77)			
•		0.02 +/- 0.01(MDA 0.06)			
		0.75 +/- 0.15			
		•••••		••••••	
Sample Number		881-10	•		
Sample Date		7-29-88			
Pu-239,240	(pCi/q)	3.5 +/- 0.4			
U-233,234		1.1. +/- 0.3			
•	(pCi/g)	0.05 +/- 0.02(MDA 0.06)			
	(pCi/g)	0.98-+/- 0.2			
n-530	(pci/g/				

881 Hillside Soil Report
Quality Assurance/Quality Control Data

E88-3019

The following data provide quality assurance and quality control for all analyses in this report with the exception of the uranium analyses of 881-7, 881-8 and 881-9.

## Reagent Blanks

Pu-239,240	(pC1/g)		0.04
U-233,234			-0.11
u-235	(pCi/g)	•	0.02
u-238	(pCi/g)		0.02

Controls	Observed	'Standard
·	<del></del> .,	
Pu-239,240 (pC1/g)	1.3 +/- 0.2	1.0
u-233,234 (pCi/g)	1.7 +/- 0.3 .	· 2.0
U-235 (pCi/g)	0.03+/- 0.08	**
u-238 (pC1/g)	1.7 +/- 0.2	2.0

The following QA/QC data applies to the uranium analyses performed on samples 881-7, 881-8 and 881-9.

## Reagent Blanks

U-233,234	(pCi/g)	-0.03
U-235	(pCi/g)	0.00
U-238	(pCi/g)	-0.02

Controls		Observed	Standard
U-233,234	(pCi/g)	1.1 +/- 0.3	1.1
U-235	(pCi/g)	0.06+/- 0.02	**
บ-238	(pCi/g)	1.1 +/- 0.2	1.1

<sup>\*\*</sup> National Bureau of Standards does not provide a certified value for U-235 activity in this standard.